



WIRING FOR TOROID TRANSFORMERS

WIRING	380-
COLOUR	440
WIRE A	RED
WIRE B	RED
WIRE C	BRN
WIRE D	BLU
TRANSFORMER VOLTAGE	0-240

NOT VALID FOR TOROID TRANSFORMERS (SEE TABLE ABOVE)

VARISTOR CONNECTED BETWEEN C1:1 AND C2:13

Ⓞ: IMPORTANT: REMOVE CONNECTION ON THE OVERLOAD RELAY BEFORE MOUNTING

Ⓢ: CONNECT TO THE TERMINAL BLOCK



RG-400i ELECTRICAL DIAGR.
380-440 3 50/60 WITH NEUTRAL WIRE

Dwn by TF	Rev.date 1502:
Appr. TF	Date 1502:
Drawing no.	37136